

Deficiency SHW027 Photos – Facility 207



Building Interior



Building Interior Water Damage



Building Entrance



Building Exterior

Deficiency SHW036 Photos – Facility 207TBD



Fill Stand Exposed to Elements

Deficiency SHW037 Photos – Facility 207TBD



Filter Equipment Pad Exposed to Elements

Deficiency SHW057 Photos – Facility 9300TBD



Housekeeping Pad on Plan North Side of Shaw Drive



Housekeeping Pad on Plan South Side of Shaw Drive